

Release notes TWEB4

These release notes are applicable to the following modules:

- 2EB24

Software version 0404
Hardware version 0100
Platform TWEB4
Date 07-12-2010
Filename 2EB24-0100-0404-service.zip

Fixed EDH errors on channel B (caused by latest SDRAM revision)

Software version 0403
Hardware version 0100
Platform TWEB4
Date 09-01-2010
Filename 2EB24-0100-0403-service.spf

Added +22dBu item to 0dBFS-In_A and 0dBFS-In_B

Software version 0303
Hardware version 0100
Platform TWEB4
Date 26-10-2009
Filename 2EB24-0100-0303-service.spf

Solved: swapped audio-channels in embedder-core when switching SDI-Input-sources using a specific timing.

Software version 0302
Hardware version 0100
Platform TWEB4
Date 21-02-2006
Filename 2EB24-0100-0302-service.spf

- Solved audio cracks when audio-delay > 683ms

Software version 0201
Hardware version 0100
Platform TWEB4
Date 02-02-2006
Filename 2EB24-0100-0201-service.spf

0dBFS_In_A/B: This setting was not working correctly (Analog audio input-level-conversion +12/+15/+18/+24dBu -> dBFS)

Software version 0101
Hardware version 0100
Platform TWEB4
Date 24-11-2005
Filename 2EB24-0100-0101-service.spf

First release
