

Release notes SYLA1-SYLA1,SYLA2

These release notes are applicable to the following modules:

- DIO88

Software version 0206
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 24-08-2018
Filename DIO88-0100to0200-0206-service.zip

- Quad speed audio output 2 (slot2) not reacting to menu item.

Software version 0205
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 19-12-2014
Filename DIO88-0100to0200-0205-service.zip

- Error generator added to test announcements
- Improved announcement handling

Software version 0104
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 21-05-2013
Filename DIO88-0100to0200-0104-service.zip

- input

Software version 0102
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 25-04-2012
Filename DIO88-0100to0200-0102-service.zip

AES input change will reset all inputs to perform an sample perfect phase alignment

Software version 0103
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 22-05-2012
Filename DIO88-0100to0200-0103-service.zip

- input 13/14 did not react to menu item. solved in 0103

Software version 0102
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 25-04-2012
Filename DIO88-0100to0200-0102-service.zip

AES input change will reset all inputs to perform an sample perfect phase alignment

Software version 0101
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1
Date 24-05-2011
Filename DIO88-0100to0200-0101-service.zip

first release
