

Release notes SYRC08

These release notes are applicable to the following modules:

- ERC108
- ERS108
- MRC04
- MRS04

Software version 2201
Hardware version 0101, 0102
Platform SYRC08
Date 01-05-2018
Filename erc108-0101to0102-2201-service.zip

Fixes
- SNMP: fixed set long object numbers

Software version 2101
Hardware version 0101, 0102
Platform SYRC08
Date 22-01-2018
Filename erc108-0101to0102-2101-service.zip

Fixes
- SNMP: fixed timing issue for slower cards
- TCP: close connection on disconnect

Software version 2001
Hardware version 0101, 0102
Platform SYRC08
Date 16-05-2017
Filename erc108-0101to0102-2001-service.zip

Fixes
- SNMP: fixed time out
- SFP status reset with new programming
- Announcements for Temperature/Voltage/Current reduced

Software version 1901
Hardware version 0101
Platform SYRC08
Date 28-07-2016
Filename erc108-0101-1901-service.zip

Fixes
- Redundant network support
- USB-relay box support
- Fixed glitch in the Ref power selection upon powerup

Software version 1801
Hardware version 0101
Platform SYRC08
Date 18-04-2016
Filename erc108-0101-1801-service.zip

Fixes
- correct NTP status when no servers available

Software version 1701
Hardware version 0101
Platform SYRC08
Date 19-02-2016
Filename erc108-0101-1701-service.zip

Fixes
- Ref-Relais is restored to the state it was before power down

Software version 1601
Hardware version 0101
Platform SYRC08
Date 25-11-2015
Filename erc108-0101-1601-service.zip

Fixes
- Correct functioning of multiple NTP server connections

Software version 1401
Hardware version 0101
Platform SYRC08
Date 12-05-2015
Filename erc108-0101-1401-service.zip

Fixes
- Upgrade of multiple cards fixed
- SNMP fixes for incorrect requests
- Ref relais default on Main power
- Frame departure fixed

Software version 1201
Hardware version 0101
Platform SYRC08
Date 13-08-2014
Filename erc108-0101-1201-service.zip

Fixes :
Improved card handling at powering up
Added Card removed state

Software version 1101
Hardware version 0101
Platform SYRC08
Date 24-06-2014
Filename erc108-0101-1101-service.zip

Fixes :
Ethernet Link LED at every speed
Hide unavailable status items in Cortex
Tacho speed check for front tray fan
SNMP value of long objects

Software version 1001
Hardware version 0101
Platform SYRC08
Date 05-02-2014
Filename erc108-0101-1001-service.zip

Fixes :
- Ethernet Link led no on for all speeds
- Reduced number of temperture announcements
- NTP broadcast on internal bus fixed

Added :
- Option for temperature and fan sensors on Rear (Left and Right) and Fan Tray
- Keyable to MRC04 and MRS04 (Mobile)

Software version 0901
Hardware version 0101
Platform SYRC08
Date 27-06-2013
Filename erc108-0101-0901-service.zip

Added USB-Relay control
Fix SNMP Enterprise object ID

Software version 0801
Hardware version 0101
Platform SYRC08
Date 06-11-2012
Filename erc108-0101-0801-service.zip

Improved EEPROM write: this fixes problems writing keys on some ERC cards
SNMP: fix card removal issue
SNMP: fix card order issue
