



Restricted Delivery Announcement

The product(s) below may be delivered to customers with the deviations or restrictions mentioned hereafter. Within the limits of the restrictions, all essential points of the applicable specifications have been satisfied; the samples from production have been accepted and suitable measures have been taken to keep outgoing quality at an acceptable level. The service organization can provide adequate support. All necessary measures have been taken to ensure product safety and EMC.

Applies to

Firmware version 0506 of:

- **GDB5XX – HDB5XX**
- **GDB9XX – HDB9XX**

A Synapse® product

Deviations from technical specification or other restrictions

- Feature still to be added
 - Silence detection for audio
- Not locking to reference in 1080p23.98
- No 1080PsF23.98 video output. In 1080PsF23.98 audio de-embedding using pre-delay setting is working.
- This firmware version incorporates a S2020 Beta release
- It is possible there are artifacts shown while switching between sources when locked to reference due to an error in the autophaser.

Expected roadmap for fix

Please consult Axon product management for this roadmap.