

Release notes SYHDV1,SYHDV2-SYHDV2

These release notes are applicable to the following modules:

- HDV100

Software version 1010
Hardware version 0102, 0103, 0104, 0105
Platform SYHDV1,SYHDV2
Date 12-11-2014
Filename HDV100-0102to0105-1010-service.zip

Merged firmware for hardware version 0102 to 0104 with firmware for hardware version 0105
No functionality changes with reference to firmware version 0910

Software version 0910
Hardware version 0105
Platform SYHDV2
Date 16-10-2014
Filename HDV100-0105-0910-service.zip

bug fix y/c delay

Software version 0809
Hardware version 0105
Platform SYHDV2
Date 19-07-2013
Filename HDV100-0105-0809-service.zip

Firmware update due to hardware redesign (replaced obsolete CVBS encoder)

Software version 0709
Hardware version 0102, 0103, 0104
Platform SYHDV1,SYHDV2
Date 25-02-2013
Filename HDV100-0102to0104-0709-service.zip

- Solved bug spikes in video

Software version 0708
Hardware version 0102, 0103, 0104
Platform SYHDV1,SYHDV2
Date 20-12-2012
Filename HDV100-0102to0104-0708-service.zip

- Added constant 40ms delay option
- pan pix to right so no blue line in active video

Software version 0607
Hardware version 0102, 0103, 0104
Platform SYHDV1,SYHDV2
Date 19-04-2012
Filename HDV100-0102to0104-0607-service.zip

- Initial version
