

Restricted Delivery Announcement

The product(s) below may be delivered to customers with the deviations or restrictions mentioned hereafter. Within the limits of the restrictions, all essential points of the applicable specifications have been satisfied; the samples from production have been accepted and suitable measures have been taken to keep outgoing quality at an acceptable level. The service organization can provide adequate support. All necessary measures have been taken to ensure product safety and EMC.

Applies to

Firmware version 0902 of:

- **GFS-HFS110-100-010**

A Synapse® product

Deviations from technical specification or other restrictions

- Audio clics occur if video input A is routed to video output B
- Setting autoformat is not working
- If timecode is inserted and audio handling is set to transparent, timecode can be lost.

Expected roadmap for fix

Please consult Axon product management for this roadmap.