

# Release notes SYLA1,SYLA2

These release notes are applicable to the following modules:

- DDP94

---

**Software version** 0506  
**Hardware version** 0100, 0101, 0102, 0200  
**Platform** SYLA1,SYLA2  
**Date** 23-11-2015  
**Filename** DDP94-0100to0200-0506-service.zip

- added pcm delay for backup channel

---

**Software version** 0405  
**Hardware version** 0100, 0101, 0102, 0200  
**Platform** SYLA1,SYLA2  
**Date** 23-05-2013  
**Filename** DDP94-0100to0200-0405-service.zip

- changed quadspeed input bus location

---

**Software version** 0404  
**Hardware version** 0100, 0101, 0102, 0200  
**Platform** SYLA1,SYLA2  
**Date** 21-05-2013  
**Filename** DDP94-0100to0200-0404-service.zip

- changed quadspeed mux position. solved bug 2254  
- intended to use with dolby version 2407  
- rev mode for metadata is default last valid.

---

**Software version** 0403  
**Hardware version** 0100, 0101, 0102, 0200  
**Platform** SYLA1,SYLA2  
**Date** 18-01-2013  
**Filename** DDP94-0100to0200-0403-service.zip

- transcoding startup  
- fixed datarate 7.1  
- intended to use with version 2407

**Software version** 0303  
**Hardware version** 0100, 0101, 0102, 0200  
**Platform** SYLA1,SYLA2  
**Date** 26-06-2012  
**Filename** DDP94-0100to0200-0303-service.zip

- Datarate issue HE-AAC solved
  - intended to use with version 2403
  - added warble tone mixing
  - added AD mixing
- 

**Software version** 0202  
**Hardware version** 0100, 0101, 0102, 0200  
**Platform** SYLA1,SYLA2  
**Date** 11-1-2012  
**Filename** DDP94-0100to0200-0202-service.zip

- Added support for DD and DDplus combined
  - intended to use with version 2232
- 

**Software version** 0102  
**Hardware version** 0100, 0200, 0200  
**Platform** SYLA1,SYLA2  
**Date** 1-11-2011  
**Filename** DDP94-0100to0200-0102-service.zip

- initial release
  - intended to use with version 2232
-