

Release notes SYRC18

These release notes are applicable to the following modules:

- ERC118
 - ERS118
-

Software version 2201
Hardware version 0301, 0302, 0303
Platform SYRC18
Date 01-05-2018
Filename erc118-0301to0303-2201-service.zip

Fixes
- SNMP: fixed set long object numbers

Software version 2101
Hardware version 0301, 0302, 0303
Platform SYRC18
Date 22-01-2018
Filename erc118-0301to0303-2101-service.zip

Fixes
- SNMP: fixed timing issue for slower cards
- TCP: close connection on disconnect

Software version 2001
Hardware version 0301, 0302, 0303
Platform SYRC18
Date 16-05-2017
Filename erc118-0301to0303-2001-service.zip

Fixes
- SNMP: fixed time out
- SFP status reset with new programming
- Announcements for Temperature/Voltage/Current reduced

Software version 1901
Hardware version 0301, 0302, 0303
Platform SYRC18
Date 28-07-2016
Filename erc118-0301to0303-1901-service.zip

Fixes
- Redundant network support
- USB-relay box support
- Fixed glitch in the Ref power selection upon powerup

Additions
- Support for GEN3 frontpanel and fan tray
- Support for SMP175 power supply

Software version 1801
Hardware version 0301, 0302
Platform SYRC18
Date 18-04-2016
Filename erc118-0301to0302-1801-service.zip

Fixes
- correct NTP status when no servers available

Software version 1701
Hardware version 0301, 0302
Platform SYRC18
Date 19-02-2016
Filename erc118-0301to0302-1701-service.zip

Fixes
- Ref-Relais is restored to the state it was before power down

Software version 1601
Hardware version 0301, 0302
Platform SYRC18
Date 25-11-2015
Filename erc118-0301to0302-1601-service.zip

Fixes
- Correct functioning of multiple NTP server connections

Software version 1401
Hardware version 0301, 0302
Platform SYRC18
Date 12-05-2015
Filename erc118-0301to0302-1401-service.zip

Fixes
- Upgrade of multiple cards fixed
- SNMP fixes for incorrect requests
- Ref relais default on Main power
- Frame departure fixed

Software version 1201
Hardware version 0301
Platform SYRC18
Date 13-08-2014
Filename erc118-0301-1201-service.zip

Fixes :
Improved card handling at powering up
Added Card removed state

Software version 1101
Hardware version 0301
Platform SYRC18
Date 24-06-2014
Filename erc118-0301-1101-service.zip

Fixes :
Ethernet Link LED at every speed
Tacho speed check for front tray fan
SNMP value of long objects

Software version 1001
Hardware version 0301
Platform SYRC18
Date 05-02-2014
Filename erc118-0301-1001-service.zip

Ethernet Link led no on for all speeds
Reduced number of temperture announcements
NTP broadcast on internal bus fixed

Software version 0901
Hardware version 0301
Platform SYRC18
Date 27-06-2013
Filename erc118-0301-0901-service.zip

Added USB-Relay control
Fix SNMP Enterprise object ID

Software version 0801
Hardware version 0301
Platform SYRC18
Date 06-11-2012
Filename erc118-0301-0801-service.zip

Improved EEPROM write: this fixes problems writing keys on some ERC cards
SNMP: fix card removal issue
SNMP: fix card order issue
