

Release notes HDH20

These release notes are applicable to the following modules:

- HSU05

Software version 2324
Hardware version 0101, 0102, 0103, 0104, 0105, 0106
Platform HDH20
Date 02-02-2017
Filename HSU05-0101to0106-2324-service.zip

Fixed: Broken audio on add-on bus.

Software version 2323
Hardware version 0101, 0102, 0103, 0104, 0105, 0106
Platform HDH20
Date 13-01-2017
Filename HSU05-0101to0106-2323-service.zip

Fixed: Pixel errors fixed by improving memory timing.

Software version 2322
Hardware version 0101, 0102, 0103, 0104, 0105, 0106
Platform HDH20
Date 17-12-2010
Filename HSU05-0101to0106-2322-service.zip

- Added Panic Freeze function
- Fixed: Audio tick on de-embedded audio
- Fixed: H and V reference timing behavior

Software version 2221
Hardware version 0101, 0102, 0103, 0104, 0105, 0106
Platform HDH20
Date 03-06-2010
Filename HSU05-0101to0106-2221-service.zip

Initial Release