

# Release notes ASM10-ASM10,SYAS2

These release notes are applicable to the following modules:

- ASM10

---

**Software version** 1411  
**Hardware version** 0100, 0101, 0102, 0103, 0200, 0201, 0202, 0203  
**Platform** ASM10,SYAS2  
**Date** 10-07-2014  
**Filename** ASM10-0100to0203-1411-service.zip

Fixed: video hiccups

---

**Software version** 1410  
**Hardware version** 0100, 0101, 0102, 0103, 0200, 0201, 0202  
**Platform** ASM10,SYAS2  
**Date** 06-05-2014  
**Filename** ASM10-0100to0202-1410-service.zip

analog video changed to free\_run input  
teletext In 8 is passthrough

---

**Software version** 1309  
**Hardware version** 0100, 0101, 0102, 0103, 0200, 0201, 0202  
**Platform** ASM10,SYAS2  
**Date** 11-10-2012  
**Filename** ASM10-0100to0202-1309-service.zip

- V phase and H phase was not working in previous versions

---

**Software version** 1209  
**Hardware version** 0100, 0101, 0102, 0103, 0200, 0201  
**Platform** ASM10,SYAS2  
**Date** 15-6-2011  
**Filename** ASM10-0100to0201-1209-service.spf

- phase alignment added

---

**Software version** 1108  
**Hardware version** 0100, 0101, 0102, 0103, 0200, 0201  
**Platform** ASM10,SYAS2  
**Date** 28-10-2009  
**Filename** ASM10-0100to0201-1108-sevice.spf

- Pal M correct subcarrier  
- Auto Backup added

---

**Software version** 1008  
**Hardware version** 0100, 0101, 0102, 0103, 0200  
**Platform** ASM10,SYAS2  
**Date** 05-08-2009  
**Filename** ASM10-0100to0200-1008-service.spf

- Improved settings on CVBS decoder chip

---

**Software version** 0908  
**Hardware version** 0100, 0101, 0102, 0103, 0200  
**Platform** ASM10,SYAS2  
**Date** 26-06-2009  
**Filename** ASM10-0100to0200-0908-service.spf

- Hue control now available for both analog and SD SDI inputs

---

**Software version** 0807  
**Hardware version** 0100, 0101, 0102, 0103, 0200  
**Platform** ASM10,SYAS2  
**Date** 17-03-2009  
**Filename** ASM10-0100to0200-0807-service.spf

- Ensures backwards compatibility

---

**Software version** 0707  
**Hardware version** 0100, 0101, 0102, 0103, 0200  
**Platform** ASM10,SYAS2  
**Date** 19-12-2008  
**Filename** ASM10-0100to0200-0707-service.spf

- SW\_OUT\_OFF added to input loss menu item.

---

**Software version** 0606  
**Hardware version** 0100, 0101, 0102, 0103, 0200  
**Platform** ASM10,SYAS2  
**Date** 02-11-2007  
**Filename** ASM10-0100to0200-0606-service.spf

- Fixed: V-delay and H-delay don't hold the value after powercycle.

---

**Software version** 0506  
**Hardware version** 0100, 0101, 0102, 0103  
**Platform** ASM10  
**Date** 12-07-2007  
**Filename** asm10-0100to0103-0506-service.spf

- Fixed: V-delay and H-delay don't hold the maximum value for 625 after powercycle

---

**Software version** 0406  
**Hardware version** 0100, 0101, 0102, 0103  
**Platform** ASM10  
**Date** 21-03-2007  
**Filename** asm10-0100to0103-0406-service.spf

- Freeze fixed at analog input-loss  
- Power dissipation decreased

---

**Software version** 0305  
**Hardware version** 0100, 0101, 0102, 0103  
**Platform** ASM10  
**Date** 23-11-2006  
**Filename** asm10-0100to0103-0305-service.spf

Improved stability memory timing  
Corrected timing according to reference

---

**Software version** 0304  
**Hardware version** 0100, 0101, 0102, 0103  
**Platform** ASM10  
**Date** 05-04-2006  
**Filename** ASM10-0100to0103-0304-service.spf

Position of gain blok has changed to behind de-embedder and local input. So, it is possible to gain the de-embedded audio too.

**Software version** 0303  
**Hardware version** 0100, 0101, 0102, 0103  
**Platform** ASM10  
**Date** 07-03-2005  
**Filename** ASM10-0100to0103-0303-service.spf

- strnrd NTSC to Auto NTSC
  - strnrd PAL to Auto PAL
  - digital format is only for SDI not for CVBS zie ASV21
  - Cont analog voor badVCR input
  - audio delay offset
  - YC input added
  - Solved not hold setting when used with setup
- 

**Software version** 0202  
**Hardware version** 0100, 0101, 0102, 0103  
**Platform** ASM10  
**Date** 07-01-2005  
**Filename** ASM10-0100to0103-0202-service.spf

- in delay mode the delay went from 0 to minmaal
  - announcement filter for analog audio input
  - menu setting Tracking Off is removed
- 

**Software version** 0101  
**Hardware version** 0100, 0101, 0102, 0103  
**Platform** ASM10  
**Date** 24-11-2004  
**Filename** ASM10-0100to0103-0101-service.spf

First release

---