

Release notes SYTXG1

These release notes are applicable to the following modules:

- GMD100

Software version 0308
Hardware version 0402, 0403, 0404
Platform SYTXG1
Date 10-01-2020
Filename txg1-gmd-0402to0404-0308-service.zip

WARNING: NOT UPGRADABLE VIA RACKCONTROLLER. ONLY LOCAL VIA BACKPLANE OF THE CARD.
FOLLOW Appendix x "Reprogramming GMD100 modules" from Manual.

Solved:
- IO delay with asynchronous inputs was inconsistent.

Software version 0307
Hardware version 0402, 0403
Platform SYTXG1
Date 4-10-2017
Filename txg1-gmd-0402to0403-0307-service.zip

WARNING: NOT UPGRADABLE VIA RACKCONTROLLER. ONLY LOCAL VIA BACKPLANE OF THE CARD.
FOLLOW Appendix x "Reprogramming GMD100 modules" from Manual.

Solved:
- ATC type selection now selects correctly between VITC and LTC.

Software version 0306
Hardware version 0402, 0403
Platform SYTXG1
Date 17-06-2016
Filename txg1-gmd-0402to0403-0306-service.zip

WARNING: NOT UPGRADABLE VIA RACKCONTROLLER. ONLY LOCAL VIA BACKPLANE OF THE CARD.
FOLLOW Appendix x "Reprogramming GMD100 modules" from Manual.

Added:
- S352 payload insert enable. This is to disable the payload when it conflicts with ATC type LTC transparency.
- ATC type VITC transparency.
Solved:
- Time code jump error. Jumps outside 40 sec where not detected.
- Time code calculations outside one hour.
- ATC timecode detection corrected.

Software version 0203
Hardware version 0402, 0403
Platform SYTXG1
Date 29-03-2016
Filename txg1-gmd-0402to0403-0203-service.zip

WARNING: NOT UPGRADABLE VIA RACKCONTROLLER. ONLY LOCAL VIA BACKPLANE OF THE CARD.
FOLLOW Appendix x "Reprogramming GMD100 modules" from Manual.

Added ATC type selection
Added Hold to TC_Align_Set options
Fine tuned the audio video delay alignment
Status of Input B in .clf file corrected
Changed input selection in blockschematic PD and manual

Software version 0102
Hardware version 0402, 0403
Platform SYTXG1
Date 10-02-2016
Filename txg1-gmd-0402to0403-0102-service.zip

WARNING: NOT UPGRADABLE VIA RACKCONTROLLER. ONLY LOCAL VIA BACKPLANE OF THE CARD.
FOLLOW Appendix x "Reprogramming GMD100 modules" from Manual.

First release
