



Restricted Delivery Announcement

The product(s) below may be delivered to customers with the deviations or restrictions mentioned hereafter. Within the limits of the restrictions, all essential points of the applicable specifications have been satisfied; the samples from production have been accepted and suitable measures have been taken to keep outgoing quality at an acceptable level. The service organization can provide adequate support. All necessary measures have been taken to ensure product safety and EMC.

Applies to

Firmware version v1417 of:

- **GXG400**
- **GXG410**
- **UXU400**
- **UXU410**

A Synapse® product

Deviations from technical specification or other restrictions

Fixed:

- Updated the Dolby-Aligner, it aligns all the embedded Dolby-E streams by using the "Dolby-E Reference Line-Position recommendations" of Dolby.

Known Issues:

- Dolby E aligner only works in 50Hz Standards
- Format and Hue settings are not working for CVBS SFP modules
- Picture Position settings and Preset not implemented
- Converting OP47/s2031 from any p50 input to sd625/sd525 output doesn't work
- Converting from progressive 25hz to 1080p50 level-b doesn't work

Expected roadmap for fix

Please consult Axon product management for this roadmap.