

Release notes HDH20

These release notes are applicable to the following modules:

- HDS05

Software version 2627
Hardware version 0104, 0105, 0106
Platform HDH20
Date 28-06-2013
Filename HDS05-0104to0106-2627-service.zip

GPI local function fixed

Software version 2626
Hardware version 0104, 0105, 0106
Platform HDH20
Date 19-04-2013
Filename HDS05-0104to0106-2626-service.zip

Fixed: Delay of 2 frames before switched aspect ratio triggered by S2016
Added: Downconversion filter set

Software version 2525
Hardware version 0104, 0105, 0106
Platform HDH20
Date 26-04-2012
Filename HDS05-0104to0106-2525-service.zip

Fixed: Black line error fixed with SD_SDI in and locked to reference and the input frequency is lower than the reference frequency.

Software version 2524
Hardware version 0104, 0105, 0106
Platform HDH20
Date 22-11-2011
Filename HDS05-0104to0106-2524-service.zip

Fixed: EDH errors on the output of some cards.
Fixed: Field length errors in SD525, caused by a faulty vbit in the flags word.

Software version 2423
Hardware version 0104, 0105, 0106
Platform HDH20
Date 22-02-2011
Filename HDS05-0104to0106-2423-service.spf

Ref 1,2 selection corrected.

Software version 2323
Hardware version 0104, 0105, 0106
Platform HDH20
Date 15-11-2010
Filename HDS05-0104to0106-2323-service.zip

- Fixed bug: EDH errors in 60Hz

Software version 2222
Hardware version 0104, 0105, 0106
Platform HDH20
Date 03-06-2010
Filename HDS05-0104to0106-2222-service.zip

Initial Release
