

Release notes SYLA1,SYLA2

These release notes are applicable to the following modules:

- DDP24

Software version 0605
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 07-06-2013
Filename DDP24-0100to0200-0605-service.zip

- changed TC input to CH1/2 input so TC also works in addon mode

Software version 0505
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 23-05-2013
Filename DDP24-0100to0200-0505-service.zip

- changed quadspeed input bus. changed mux position to correct position

Software version 0504
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 21-05-2013
Filename DDP24-0100to0200-0504-service.zip

- changed quadspeed mux position. solved bug 2254
- intended to use with dolby version 2407
- rev mode for metadata is default last valid.

Software version 0403
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 8-05-2013
Filename DDP24-0100to0200-0403-service.zip

- Transcoding DD to DD+ issue's solved
- intended to use with version 2403

Software version 0303
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 26-06-2012
Filename DDP24-0100to0200-0303-service.zip

- Datarate issue HE-AAC solved
 - intended to use with version 2403
 - added warble tone mixing
 - added AD mixing
-

Software version 0202
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 11-1-2012
Filename DDP24-0100to0200-0202-service.zip

- Added support for DD and DDplus combined
 - intended to use with version 2232
-

Software version 0102
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 1-11-2011
Filename DDP24-0100to0200-0102-service.zip

- initial release
 - intended to use with version 2232
-